

## Circular 87 / 2014

To: Vessel Owners, Managers, Masters, Officers, Deputy Registrars, Surveyors and Other Interested Parties

Subject: GME-brand EPIRBs risk of failure and recall

Date: 5 August 2014

## Summary

Maritime Cook Islands draws your attention to the alerts, issued by Standard Communications Pty Ltd. attached below.

## EPIRB PRECAUTIONARY SAFETY ALERT

Summary: The following GME EPIRB models, manufactured between 2005 and 2010, have been identified as being at risk of failure: GME MT400; GME MT401; GME MT406G; GME MT401FF; GME MT403/G; and GMEMT403FF/FG.

## PRODUCT SAFETY RECALL

Summary: The following GME EPIRB models, manufactured between January 2005 and February 2008, have been recalled: MT400, MT401 and MT403 beacons with serial numbers between 50101000 and 80250722.

For further information or clarification please contact the Registrar of Ships, a Deputy Registrar or Fleet Manager at Maritime Cook Islands; alternatively you may contact Maritime Cook Islands Head Office at +682 23848 Phone, +682 23846 Fax, fleet@maritimecookislands.com

Please ensure this has been forwarded to interested parties.